

**From:** [Axtman, John S.](#)  
**To:** [Tricia Pfeiffer](#)  
**Subject:** Re: fence-Oasis sites  
**Date:** 06/19/2012 06:11 PM

---

The well in the picture appears to be a Statoil well. Not an Oasis well. I have contacted Statoil and they are checking to see if they can determine what well this is. When I get more information I will get back to Jackie.

John

Sent from my iPhone

On Jun 19, 2012, at 5:32 PM, "Tricia Pfeiffer" <[Pfeiffer.Tricia@epamail.epa.gov](mailto:Pfeiffer.Tricia@epamail.epa.gov)> wrote:

Hey John,

Thanks for following up. I don't think what you are referring to being sent to Jacki got attached. Did you let Jacki know what type of follow up you have underway? I think it would be helpful if we could keep her informed of any follow ups that are underway, otherwise she may think that we are not being responsive.

Just curious, did the inspector figure out if there is an issue at the site re:the combustion process or other that could produce the black smoke seen in the picture submitted?

Thanks,  
Tricia

Tricia Rios Pfeiffer, Engineer  
U.S. Environmental Protection Agency-Region8  
Watershed & Aquifer Protection Unit  
1595 Wynkoop Street  
MC: EP-EPR  
Denver, Colorado 80202

P: 303-312-6271  
P: 866-457-2690 ext 312-6271  
F: 303-312-7206

<graycol.gif> "Axtman, John S." ---06/18/2012 12:38:35 PM---Tricia I sent this to Jackie today. I just talked to an inspector that was was on location about 1

From: "Axtman, John S." <[jaxtman@nd.gov](mailto:jaxtman@nd.gov)>  
To: Tricia Pfeiffer/R8/USEPA/US@EPA  
Date: 06/18/2012 12:38 PM  
Subject: Fwd: fence-Oasis sites

---

Tricia I sent this to Jackie today. I just talked to an inspector that was was on

location about 1 hour ago. I will ask if she saw any gas venting.

Sent from my iPhone

Begin forwarded message:

**From:** "Axtman, John S." <[jaxtman@nd.gov](mailto:jaxtman@nd.gov)>  
**Date:** June 18, 2012 9:43:29 AM CDT  
**To:** jacki <[jboid@dia.net](mailto:jboid@dia.net)>  
**Subject:** FW: fence-Oasis sites

We are looking into it. Well is surrounded by stubble fields on all sides and there is no fence around any of those fields. I would say the major danger for both livestock and humans is the cows getting out on the road and causing an accident that could result in property damage and or injury to both animals and humans.

Keith Oyloe  
Production Manager  
Oasis Petroleum  
5437 137<sup>th</sup> Ave NW  
Williston, ND 58801  
Office Phone: 701-577-1613  
Cell Phone : 701-580-4047

**From:** Axtman, John S. [<mailto:jaxtman@nd.gov>]  
**Sent:** Wednesday, June 13, 2012 2:17 PM  
**To:** Keith Oyloe  
**Subject:** Fwd: fence-Oasis sites

Sent from my iPhone

Begin forwarded message:

**From:** jacki <[jboid@dia.net](mailto:jboid@dia.net)>  
**Date:** June 13, 2012 12:28:18 PM CDT  
**To:** "Axtman, John S." <[jaxtman@nd.gov](mailto:jaxtman@nd.gov)>  
**Cc:** "[pfeiffer.Tricia@epamail.epa.gov](mailto:pfeiffer.Tricia@epamail.epa.gov)"  
<[pfeiffer.Tricia@epamail.epa.gov](mailto:pfeiffer.Tricia@epamail.epa.gov)>  
**Subject:** fence-Oasis sites

Did you ever get a status yesterday on the fence problem out here on the Ellis-Somerset site? The tank under the open chemical barrels just happens to be the same kind of stock tanks I use for watering the cattle- they are attracted to it like a magnet. There needs to be some type of a cover over this stock tank used on the well site. This tank is in open access for livestock and wildlife to "drink" any fluids that may be in the tank. The pipeline crew working in the area could not locate a fence around this or other sites out here. They reported cattle being on the site.

recipient's agent, you are hereby notified that any review, use, dissemination, distribution or copying of this communication is strictly prohibited. You are also asked to notify the sender immediately by telephone and to delete this transmission with any attachments and destroy all copies in any form. Thank you in advance for your cooperation.